




HYPERTOOL SCRIPTS



HYPERTOOL SCRIPTS



HYPERTOOL SCRIPTS




HYPERTOOL SCRIPTS

Miscellaneous Scripts	Oneup Drawing	30
	Find Copper Area	31
	Surface finish Area	32
	Score Layer Template Creation	33
	Score sheet PDF merge	34
	Plotparameter	35
	Edit Zip Tool	36
	FTP Upload	37
	PNG Snap	38
	Trigonometric Functions	39
	Unpierce (UL Requirement)	40
Array	Tooling Holes and Fiducials	41
	Copper Balance	42
	Outer Rout Retraction Attribute	43



HYPERTOOL SCRIPTS



HYPERTOOL SCRIPTS

Crosscheck Scripts	Quality check	52
	Origin Check	53
	Invalid Arc Check	54
	Drill Optimisation Check	55
	Markings Check	56
	EC Check	57
	274x-Gerber Output check	58
	Gold finger connection check	59
	DIS Overlap Check	60
	Panel Size and No.of circuits/panel check	61
Technology	Gold finger connection	62
	IPC Coupon Edit	63
	Snowmen Hit Editing	64
	Panel coupon	65
	Impedance coupon Designer	66

